## **RECALL NOTICE FROM RING**

## RING VIDEO DOORBELLS (2ND GENERATION) SOLD FROM JUNE 2020 TO OCTOBER 2020

Battery Can Overheat When Wood Screws Are Used For Installation Instead Of Security Screws, Posing Fire And Burn Hazards to Consumers.



## Updated Instructions Available. If the doorbell is installed correctly, there is no risk to consumers.

To Receive Updated Installation Instructions Call Ring at 1-800-656-1918 from 5 a.m. to 9 p.m. PT, Seven Days a Week, or Visit our Website at <a href="www.ring.com">www.ring.com</a> or App.